

ADT

Automatic Torque Drive Technology

Teknologi Tork Automatik 自动扭力驱动科技

Automatically changes the cutting speed according to load conditions for an optimum operation:

- On light duty: high-speed rotation mode
- On heavy duty: high torque mode

Fungsi pertukaran kalajuan automatik:

- Pada tugas ringan: mod putaran berkelajuan tinggi
- Pada tugas berat: mod tork tinggi

自动变速功能:

- 轻载: 高速旋转模式
- 重载: 高扭矩模式

